
User's Manual

IM CW240P-E

CW240 Clamp-on Power Meter

Quick Setup Manual

Index

Introduction	1
Precautions for Safe Use of the CW240	2
1. Part Names and How to Use Parts	1-1
1.1 Part Names and How to Use Parts	1-1
1.2 Screen Configuration	1-2
1.3 Operation Keys	1-8
2. Preparation for Measurements	2-1
2.1 Connecting a Power Supply	2-1
2.2 Connecting Voltage Probes and Current Probes	2-2
2.3 Inserting a PC Card into the CW240	2-4
2.4 Turning ON the Power Switch	2-5
3. General Settings	3-1
4. Wiring	4-1
4.1 Displaying Wiring Diag. screen	4-1
4.2 Wiring	4-2
4.3 Checking Wiring	4-3
5. Measurements	5-1
5.1 Measuring an instantaneous value	5-1
5.2 Measuring Electric Energy (Integration Measurement)	5-5
5.3 Measuring Harmonics	5-13
5.4 Displaying Waveform	5-18
5.5 Measuring Voltage Qualit (Voltage Fluctuation)	5-21
6. Troubleshooting	6-1
7. Memory Capacity (for Reference)	7-1
8. Check Sheets	8-1

Introduction

Thank you for purchasing our CW240 Clamp-on Power Meter.

This Quick Setup Manual briefly describes the key operations as well as setting examples of the CW240 upon actual measurement, so that you can operate the CW240 for the first time.

In addition to this manual, the User's Manual is available separately.
The User's Manual describes in detail the features and functions of the CW240
as well as safety measurements using the CW240.
Use the in-depth User's Manual together with this Quick Setup Manual.

After reading this manual, always keep it in an easily accessible convenient place for later reference. This manual will come in handy when you are unsure of how to operate the CW240.

Precautions for Safe Use of the CW240

The following safety symbols are used on the CW240 and in this manual.

WARNING

Indicates a hazard that may result in the loss of life or serious injury of the user unless the described instructions is abided by.

CAUTION

Indicates a hazard that may result in an injury to the user and/or physical damage to the product or other equipment unless the described instructions is abided by.

NOTE


Indicates information that is essential for handling the instrument or should be noted in order to familiarize yourself with the instrument's operating procedure and/or functions.

TIP

Indicates information that complements the present topic.

1. Part Names and How to Use Parts

1.1 Part Names and How to Use Parts




► For more details, refer to the CW240 User's Manual ◀

Chapter 2, "Part Names and How to Use Parts"

1.2 Screen Configuration

Basic Screen Configuration





► For more details, refer to the CW240 User's Manual ◀


Section, "2.4 Screen Configuration"

Displaying Measure Screen

● How to Display Measure Screen

	<p>Press the TOP MENU key.</p> 
	<p>Using the cursor key, select the MEASURE icon (highlighted).</p>
	<p>Press the ENTER key to display the Measure screen.</p>  <p>(The List screen is used as an example.)</p>

● Description of Display






► For more details, refer to the CW240 User's Manual ◀


Section 7.2.2, "Description of Display"

Displaying Setup Screen

● How to Display Setup Screen

	Press the TOP MENU key. The Top Menu screen appears. 
	Using the cursor key, select the SETUP icon (highlighted).
	Press the ENTER key to display the top Setup screen.  Select processing.
	Using the cursor key, select VARIOUS SETUP (highlighted).
	Press the ENTER key to display the Setup screen.  (The List screen is used as an example.)

● Description of Display



<Items consisting of Setup screen>

General 1/2,
General 2/2,
Save 1/2,
Save 2/2,
Communication,
Volt. Quality,
Hardware,
Analog I/O
(optional)


Description of Mark Indication

	Appears if a voltage overrange occurs.
	Appears if a current overrange occurs.
	Appears when integration measurement is made by external input control.
	Appears in the event of loss of PLL synchronization. This automatically selects the fixed clock.
	Appears when a reactive power meter method is used.
	Appears when display hold is enabled.
	Appears if the amount of data exceeds the capacity of a PC card or the internal memory.
	Appears when the CW240 is configured so that data is saved in a PC card. Also, this mark blinks during an access to the PC card.
	Appears when data has been saved in the backup memory.
	Appears when the CW240 is configured so that data is saved in the internal memory. Also, this mark blinks during an access to the internal memory.
	Appears if the CW240 is in a key lock state.
	Appears when the CW240 is configured so that the RS-232 connection destination is a PC. Also, this mark blinks during communication with the PC.
	Appears if the CW240 is configured so that the RS-232 connection destination is a printer. Also, this mark blinks during communication with the printer.
	Appears if the CW240 is powered through the AC adapter.
	Appears when the CW240 is powered through alkaline batteries or a NiMH battery pack. This mark indicates a battery voltage reduction (remaining capacity) in four steps.
	
	
	

► For more details, refer to the CW240 User's Manual ◀

Section 2.6, "Description of Mark Indication"

1.3 Operation Keys



Key Name	Functional Description
Function keys F1 to F5	These are setting keys corresponding to the information displayed in the bottom of the screen.
START & STOP key	Starts/stops integration measurements.
LIGHT key	Turns the backlight ON/OFF. When held down for more than 3 seconds, it locks or unlocks the operation keys.
TOP MENU key	Switches the display screen to the Top Menu
ESC key ENTER key	Cancels setup conditions or other data. Confirms setup conditions or other data.
Cursor key	Moves the cursor to the item you wish to select.
U RANGE key	Changes the voltage range.
A RANGE key	Changes the current range.
SAVE key	Manually save or print measured data.
DISP COPY key	Hard-copies information displayed on the screen. Copy destination setting: PC card, internal memory, or printer


► For more details, refer to the CW240 User's Manual ◀

Section 2.2, "Operation Keys"

2. Preparation for Measurements

2.1 Connecting a Power Supply

Connect the AC adapter.




As backup power supply during a power failure, one of the following batteries can be used. Use it together with the AC adapter.

- Alkaline batteries (supplied)
- NiMH battery pack (optional)

► For more details, refer to the CW240 User's Manual ◀

Section 3.2, "Connecting a Power Supply"

2.2 Connecting Voltage Probes and Current Probes




► For more details, refer to the CW240 User's Manual ◀

Section 3.3, "Connecting Voltage Probes"
Section 3.4, "Connecting Clamp-on Probes"

<Example of three-phase three-wire two-current>

**Single load of three-phase
three-wire two-current (3P3W2I)
<Two-power-meter method>**




► For more details, refer to the CW240 User's Manual ◀

Section 3.5, "Connection Diagrams of Voltage Probes and Clamp-on Probes"

2.3 Inserting a PC Card into the CW240

<Insertion method>



● Insertion Method

With the front surface of the card facing up (the direction the arrow is pointing), insert the PC card securely into the PC card slot on the side of the CW240.

► For more details, refer to the CW240 User's Manual ◀

Chapter 11, "PC Card"

● Saving Data to PC Card

- Data can be saved to the PC card, as well as the CW240's internal memory.
- Setup conditions (set values) can be loaded/saved.

► For more details, refer to the CW240 User's Manual ◀

Section 6.4, "Save Data Settings 1/2"

Section 6.5, "Save Data Settings 2/2"

Chapter 8, "Saving Measured Data"

Section 9.6, "Setting Files (Load/Save/Delete/Name Change)"

2.4 Turning ON the Power Switch


1 Model Name Screen

When the power switch is turned ON, the CW240 displays the following startup screen for approx. 2 seconds.




2 Message Screen

This screen displays the model, version number, the presence of options, and self-check results.



3

When the self-check has been completed normally, the screen displayed when you previously turned OFF the CW240 appears.



To switch to the Top Menu screen shown on the left, press the TOP MENU key.

► For more details, refer to the CW240 User's Manual ◀

Section 3.6, "Turning ON the Power Switch"


3. General Settings

Setting Up the Wiring, Number of Loads, Voltage Range, Current Range, and Clamp-on Current Probe

Example of Setting:

Setting three-phase three-wire two-current (3P3W2I) 200-V line (50 Hz, 120-A load) using the clamp-on probe 96030 (rating: 200 A)

● Displaying General Tab



► For more details, refer to the CW240 User's Manual ◀

Section 6.2, "General Settings 1/2"

Section 6.3, "General Settings 2/2"

Displaying General 1/2 Screen



Using the right and left direction cursor key, select the General tab (highlighted).

Wiring
Press the F1 key (CHANGE).
The window for selecting wiring appears.

3P3W+1P3W
3P4W4I
3P4W
3P3W3I
3P3W2I
1P3W3I
1P3W
1P2W

Using the cursor key, select a desired wiring (highlighted).

Press the ENTER key to confirm it.

SETUP 2004/06/29
11:18:21
Page 1/2

GENERAL SAVE COMMUN **WIRING** : 3P3W2I **LOAD** : LOAD1

VOLTAGE U13
U RANGE 150V
VT 1 0001.00
CURRENT CH13
A RANGE 20A
CT 1 0001.00
CLAMP 1 96030

Load
F1 : LOAD 1
F2 : LOAD 2

Voltage range
F1 : 150V
F2 : 300V
F3 : 600V
F4 : 1000V

Current range
F1 : 20A
F2 : 50A
F3 : 100A
F4 : 200A

Varies depending on the clamp-on current probe.

VT and CT ratios
Cursor key : Digit change
F1 : +
F2 : -

Model of clamp-on current probe
Press the F1 key (CHANGE).
The window for selecting model appears.

96035_02
96035_1
96034_3
96034_2
96034_1
96032
96031
96030
96033
96036


Using the cursor key, select a desired model (highlighted).

Press the ENTER key to confirm it.

Displaying General 2/2 Screen







After settings of General 1/2 has been completed, display the General 2/2 screen using the up and down direction cursor key.



4. Wiring

4.1 Displaying Wiring Diag. screen

You can carry out wiring by viewing the Wiring Diag. screen.

	<p>Displays the Measure screen.</p>  <p>TOP MENU 2004/06/25 10:49:28</p>
	<p>Press the F1 key (DISPLAY CHANGE) for window callup.</p>  <p>LIST LOAD1 INST. 2004/06/25 2004/06/25 PC D+ D- WIRING LIST I1 20.00 A 3P3W1 POWER I2 20.08 A LOAD 1 INTEGRATE I3 20.03 A U 150V DEMAND Iave 20.04 A x 1.00 ZOOM PA 0.0 ° A 20A HARMONIC F 60.00 Hz PLL WAVEFORM VOLT. QUALITY DC1 0.0 mV UT 60Hz WIRING CHECK DC2 0.0 mV INTER. 30m WIRING DIAGRAM DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD</p> <p>Using the cursor key, select WIRING DIAG. (highlighted).</p>
	<p>Press the ENTER key to display the Wiring Diag. screen.</p>  <p>WIRING DIAG. 2004/06/25 14:18:12 1P3W3I LOAD1 S N 1 SOURCE L O A D U1 U2 U3 CH1 CH2 CH3 CH4 DISPLAY CHANGE</p>


4.2 Wiring

⚠ WARNING


- When attaching voltage probes to or clamping a clamp-on current probe on the circuit under test, turn off power to the circuit under test.
It is extremely dangerous to connect or disconnect a voltage probe or clamp or unclamp a clamp-on current probe without turning off the circuit under test.
- Be sure to connect voltage probes to or clamp a clamp-on current probe on the secondary side of the circuit under test, such as current limiters (circuit breakers). Should an accident such as a short occur, other circuits will be protected by these circuit breakers.

Viewing the Wiring Diag. screen, attach voltage probes to or clamp clamp-on current probes on the circuit under test.

● Actual Wiring




<Clamp-on current probe>



4.3 Checking Wiring

You can confirm whether wiring is properly carried out or not by viewing the Wiring Check screen.

	<p>Displays the Measure screen.</p>
	<p>Press the F1 key (DISPLAY CHANGE) for window callup.</p> <p>Using the cursor key, select the WIRING CHECK (highlighted).</p>
	<p>Press the ENTER key to display the Wiring Check screen.</p> <p>Wiring conditions are checked by the vector diagram and judgment results (OK/NG). If NG is shown, check its wiring.</p>
	<p>Press the F3 key to switch between MEASURE VALUE and JUDGMENT RESULT.</p>



● If the results of one or more wiring check are NG, check the following:

Results	Measures
Voltage input judgment is NG.	<ul style="list-style-type: none"> Check if the voltage probes are connected properly to the circuit under test. Check if the voltage probes are connected properly to the voltage input terminals of the meter. Check if the voltage range is appropriate to the input level.
Current input judgment is NG.	<ul style="list-style-type: none"> Check if the clamp-on current probe(s) is clamped onto the circuit under test properly. Check if clamp-on current probe(s) is connected to the current input terminal of the meter properly. Check if the current range is appropriate to the input level.
Phase difference judgment (voltage - current) is NG.	<ul style="list-style-type: none"> Check if the voltage phase sequence is correct. Check if the direction of the arrows and the phase of the clamp-on current probe(s) are correct.
Voltage phase judgment is NG.	<ul style="list-style-type: none"> Check if the voltage phase sequence is correct. Check if the circuit under test and the setting of the wiring system agree with each other.
Current phase judgment is NG.	<ul style="list-style-type: none"> Check if the direction of the arrows and the phase of the clamp-on current probe(s) are correct. Check if the circuit under test and the setting of the wiring system agree with each other.
Frequency source check is NG.	<ul style="list-style-type: none"> Check if the voltage input selected for the frequency source is stable. Check if the voltage probes selected for the frequency source are connected properly.

 **NOTE**

There may be cases where the result of the check may show what is actually correct wiring as NG and vice versa. For this reason, also check for an error in the vector diagram or measured values.

5. Measurements

5.1 Measuring an instantaneous value

1 Settings

Example:


Measuring an instantaneous value of three-phase three-wire two-current (3P3W2I) 200-V line (50 Hz, 120-A load) using the clamp-on probe 96030 (rating: 200 A)

	Displays SETUP. <p>Top Menu screen</p>
General 1/2	<p>Using the right and left direction cursor key, display the General 1/2 screen. Set up necessary items on the screen. For details, refer to Chapter 3 in this manual.</p>
General 2/2	<p>Next, using the up and down direction cursor key, display the General 2/2 screen. Also set up necessary items on the screen. For details, refer to Chapter 3 in this manual.</p>
Save 1/2	<p>Using the right and left direction cursor key, select Save 1/2 screen.</p>
Save 2/2	<p>Next, using the up and down direction cursor key, select Save 2/2 screen.</p>
	<p>This completes the settings, returning you to the Top Menu screen.</p>


2 Wiring

After the above settings have been completed, carry out wiring, referring to Chapter 4 in this manual.


3 Measurements



● List Screen



<Description of the List screen>



F2

LOAD CHANGE

The load changes the F2 key is pressed.
(For measurement of multiple loads)

F3

The item changes each time the F3 key is pressed:

For instantaneous value measurements, the AVE, MAX., and MIN. values indicate the measured values of integration measurement conducted immediately before that.
(If no integration measurement is made immediately before that, symbol ----- appears.)

*I4: 4 ch. current is displayed only when wiring are set to 1P3W3I and 3P4W4I.

● Power Screen

 	<p>Press the F1 (DISPLAY CHANGE) key to display the Power screen.</p> <p>LIST LOAD1 INST. 2004/06/30 16:46:02</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;">LIST</td> <td>I1 19.99 A</td> <td>WIRING</td> </tr> <tr> <td>I2 20.14 A</td> <td>3P3W2I</td> </tr> <tr> <td>POWER</td> <td>I3 20.01 A</td> <td>LOAD</td> </tr> <tr> <td>DEMAND</td> <td>Iave 20.05 A</td> <td>1</td> </tr> <tr> <td>ZOOM</td> <td>U 150V</td> <td>x 1.00</td> </tr> <tr> <td>HARMONIC</td> <td>A 20A</td> <td>x 1.00</td> </tr> <tr> <td>WAVEFORM</td> <td>PA 0.0 °</td> <td></td> </tr> <tr> <td>VOLT.QUALITY</td> <td>f 60.00 Hz</td> <td>PLL</td> </tr> <tr> <td>DC1 0.0 mV</td> <td>U1 60Hz</td> <td></td> </tr> <tr> <td>DC2 0.0 mV</td> <td>INTER.</td> <td>30min</td> </tr> <tr> <td colspan="3">WIRING DIAGRAM</td> </tr> <tr> <td colspan="3" style="text-align: center;">DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD</td> </tr> </table> <p>Using the cursor key, select POWER (highlighted).</p>	LIST	I1 19.99 A	WIRING	I2 20.14 A	3P3W2I	POWER	I3 20.01 A	LOAD	DEMAND	Iave 20.05 A	1	ZOOM	U 150V	x 1.00	HARMONIC	A 20A	x 1.00	WAVEFORM	PA 0.0 °		VOLT.QUALITY	f 60.00 Hz	PLL	DC1 0.0 mV	U1 60Hz		DC2 0.0 mV	INTER.	30min	WIRING DIAGRAM			DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD		
LIST	I1 19.99 A	WIRING																																		
I2 20.14 A	3P3W2I																																			
POWER	I3 20.01 A	LOAD																																		
DEMAND	Iave 20.05 A	1																																		
ZOOM	U 150V	x 1.00																																		
HARMONIC	A 20A	x 1.00																																		
WAVEFORM	PA 0.0 °																																			
VOLT.QUALITY	f 60.00 Hz	PLL																																		
DC1 0.0 mV	U1 60Hz																																			
DC2 0.0 mV	INTER.	30min																																		
WIRING DIAGRAM																																				
DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD																																				
	<p>Press the ENTER key to confirm it. The Power screen appears.</p>																																			

<Description of the Power screen>

 	<p>Q1 to Q3 : reactive power Q : total reactive power</p> <p>POWER LOAD1 INST. 2004/06/30 16:41:01</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 10%;">P1 2.599 kW</td> <td>WIRING</td> </tr> <tr> <td>P3 2.606 kW</td> <td>3P3W2I</td> </tr> <tr> <td>P 5.205 kW</td> <td>LOAD</td> </tr> <tr> <td>S1 2.998 kVA</td> <td>1</td> </tr> <tr> <td>S3 3.002 kVA</td> <td>U 150V</td> </tr> <tr> <td>S 5.205 kVA</td> <td>x 1.00</td> </tr> <tr> <td>PA1 29.9 °</td> <td>A 20A</td> </tr> <tr> <td>PA3 -29.7 °</td> <td>x 1.00</td> </tr> <tr> <td>PF1 0.867</td> <td>PLL</td> </tr> <tr> <td>PF3 -0.868</td> <td>U1 60Hz</td> </tr> <tr> <td>PF 1.000</td> <td>INTER.</td> </tr> <tr> <td>PA 0.0 °</td> <td>30min</td> </tr> <tr> <td colspan="2">DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD</td> </tr> </table> <p>PF1 to PF3 : power factors PF : average (power factor)</p>	P1 2.599 kW	WIRING	P3 2.606 kW	3P3W2I	P 5.205 kW	LOAD	S1 2.998 kVA	1	S3 3.002 kVA	U 150V	S 5.205 kVA	x 1.00	PA1 29.9 °	A 20A	PA3 -29.7 °	x 1.00	PF1 0.867	PLL	PF3 -0.868	U1 60Hz	PF 1.000	INTER.	PA 0.0 °	30min	DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD	
P1 2.599 kW	WIRING																										
P3 2.606 kW	3P3W2I																										
P 5.205 kW	LOAD																										
S1 2.998 kVA	1																										
S3 3.002 kVA	U 150V																										
S 5.205 kVA	x 1.00																										
PA1 29.9 °	A 20A																										
PA3 -29.7 °	x 1.00																										
PF1 0.867	PLL																										
PF3 -0.868	U1 60Hz																										
PF 1.000	INTER.																										
PA 0.0 °	30min																										
DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD																											

F2

LOAD CHANGE

The load changes the F2 key is pressed.

(For measurement of multiple loads)

F3

The item changes each time the F3 key is pressed:

For instantaneous value measurements, the AVE, MAX., and MIN. values indicate the measured values of integration measurement conducted immediately before that.

(If no integration measurement is made immediately before that, symbol ----- appears.)

5.2 Measuring Electric Energy (Integration Measurement)

1 Making Settings

Example:

Measuring electric energy of three-phase three-wire two-current (3P3W2I) 200-V line (50 Hz, 120-A load) using the clamp-on probe 96030 (rating: 200 A)

General 2/2



Setting Item	Description (Setting value)
Wh DISPLAY	STANDARD

Save 1/2


Setting Item	Description (Setting value)
MEASURE START	TIME
	2004/07/01 07:00
MEASURE STOP	TIME
	2004/07/03 07:00
INTERVAL TIME	5 min
DATA SAVE	PC card
FILE NAME	PLANT5


Save 2/2

Setting Item	Description (Setting value)
INTEGRATE/DEMAND	ON


	<p>Displays SETUP.</p>  <p>TOP MENU 2004/06/25 [01:49:31]</p> <p>MEASURE SETUP FILE</p>
General 1/2 General 2/2	<p>Using the right and left direction cursor key, display the General screen. Set up necessary items on the screen. For details, refer to Chapter 3 in this manual.</p>
Save 1/2 Save 2/2	<p>Using the right and left direction cursor key, select Data Save screen. Set up necessary items on the screen.</p>

<General 1/2>





<File name change>



<File name determination>



Press the ENTER key.

This changes the file name, proceeding to the Data Save screen.

NOTE

A file name will be automatically assigned if it has not been specified:


File name: 240AMXXX (XXX: 000 to 029)

< Save 2/2>

After settings of Save 1/2 has been completed, display the Save 2/2 screen using up and down direction cursor key.

Set the items to be saved to ON. (OFF if not)

Use the cursor key to select items to be saved, and press the F1 key if the items are set to ON, and the F2 key if set to OFF.



<Exiting the Save 2/2 screen>

Press the ENTER key.



The screen returns to the Top Menu screen.

 **NOTE**

- Check SAVE-TIME. This can confirm how long the data can be saved in the PC card currently installed in the PC. If the SAVE-TIME is shorter than the measurement period, delete unnecessary files in the PC card or replace the PC card with a new one having a larger capacity.
- The measured data thus set to ON are saved to the PC card for each interval time. If you still have other data to be saved, set the items to ON.

2 Confirming Settings

	<p>Displays the Measure screen.</p> <p>TOP MENU 2004/06/28 10:49:28</p> <p>MEASURE SETUP FILE</p>																																																
	<p>Press the F1 key (DISPLAY CHANGE) for window callup.</p> <p>LIST LOAD1 INST. 2004/06/28 10:49:28</p> <table border="1"> <tr><td>11</td><td>20.01</td><td>A</td><td>WIRING</td></tr> <tr><td>12</td><td>20.09</td><td>A</td><td>LOAD</td></tr> <tr><td>13</td><td>20.02</td><td>A</td><td>U 150V</td></tr> <tr><td>14</td><td>20.04</td><td>A</td><td>x 1.00</td></tr> <tr><td>15</td><td></td><td>A</td><td>20A</td></tr> <tr><td>16</td><td>0.0</td><td>°</td><td>x 1.00</td></tr> <tr><td>17</td><td>60.01</td><td>Hz</td><td></td></tr> <tr><td>18</td><td>0.0</td><td>mV</td><td>PULL</td></tr> <tr><td>19</td><td>0.0</td><td>mV</td><td>UI 60Hz</td></tr> <tr><td>20</td><td></td><td></td><td>INTER.</td></tr> <tr><td>21</td><td></td><td></td><td>30min</td></tr> <tr><td>22</td><td></td><td></td><td>HOLD</td></tr> </table> <p>DISPLAY CHANGE ITEM CHANGE SETTING CHECK</p> <p>Using the cursor key, select INTEGRATE (highlighted).</p>	11	20.01	A	WIRING	12	20.09	A	LOAD	13	20.02	A	U 150V	14	20.04	A	x 1.00	15		A	20A	16	0.0	°	x 1.00	17	60.01	Hz		18	0.0	mV	PULL	19	0.0	mV	UI 60Hz	20			INTER.	21			30min	22			HOLD
11	20.01	A	WIRING																																														
12	20.09	A	LOAD																																														
13	20.02	A	U 150V																																														
14	20.04	A	x 1.00																																														
15		A	20A																																														
16	0.0	°	x 1.00																																														
17	60.01	Hz																																															
18	0.0	mV	PULL																																														
19	0.0	mV	UI 60Hz																																														
20			INTER.																																														
21			30min																																														
22			HOLD																																														
	<p>Press the ENTER key to display the Integrate screen.</p> <p>INTEGRATE END LOAD1 2004/06/28 10:49:28</p> <table border="1"> <tr><td>W h +</td><td>0.26kWh</td></tr> <tr><td>Wh -</td><td>0.00 kWh</td></tr> <tr><td>Varh -LAG-</td><td>0.00 kvarh</td></tr> <tr><td>Varh -LEAD-</td><td>-0.00 kvarh</td></tr> <tr><td>START TIME</td><td>2004/06/30 16:42:44</td></tr> <tr><td>STOP TIME</td><td>2004/06/30 16:45:44</td></tr> <tr><td>ELAPSED TIME</td><td>0000:03:00</td></tr> <tr><td>PULL</td><td></td></tr> <tr><td>UI 60Hz</td><td></td></tr> <tr><td>INTER.</td><td>30min</td></tr> <tr><td>DISPLAY CHANGE</td><td>ITEM CHANGE</td></tr> <tr><td>SETTING CHECK</td><td>/CLEAR</td></tr> </table>	W h +	0.26kWh	Wh -	0.00 kWh	Varh -LAG-	0.00 kvarh	Varh -LEAD-	-0.00 kvarh	START TIME	2004/06/30 16:42:44	STOP TIME	2004/06/30 16:45:44	ELAPSED TIME	0000:03:00	PULL		UI 60Hz		INTER.	30min	DISPLAY CHANGE	ITEM CHANGE	SETTING CHECK	/CLEAR																								
W h +	0.26kWh																																																
Wh -	0.00 kWh																																																
Varh -LAG-	0.00 kvarh																																																
Varh -LEAD-	-0.00 kvarh																																																
START TIME	2004/06/30 16:42:44																																																
STOP TIME	2004/06/30 16:45:44																																																
ELAPSED TIME	0000:03:00																																																
PULL																																																	
UI 60Hz																																																	
INTER.	30min																																																
DISPLAY CHANGE	ITEM CHANGE																																																
SETTING CHECK	/CLEAR																																																
	<p>Press the F4 key to display the Setting Check screen.</p> <p>SET. CHECK 2004/06/28 10:49:28</p> <table border="1"> <tr><td>WIRING :3P3W2I</td><td>LOAD :LOAD1</td></tr> <tr><td>U RANGE:150V</td><td>INTER. :30min</td></tr> <tr><td>A RANGE:20A</td><td>DAT.SAVE:PC CARD</td></tr> <tr><td>NORMAL MEAS. :ON</td><td>INST. :ON</td></tr> <tr><td>HARM. MEAS. :ON</td><td>AVE. :ON</td></tr> <tr><td>E.ENERGY/DEM. :ON</td><td>MAX. :ON</td></tr> <tr><td>WAVEFORM :ON</td><td>MIN. :ON</td></tr> <tr><td>VOLT. QUALITY:OFF</td><td></td></tr> <tr><td>START TIME:MANUAL</td><td></td></tr> <tr><td>STOP TIME:MANUAL</td><td></td></tr> <tr><td>SETUP</td><td></td></tr> </table> <p>Check each item is set properly before pressing the ENTER key. This returns to the Measure (Integrate) screen.</p>	WIRING :3P3W2I	LOAD :LOAD1	U RANGE:150V	INTER. :30min	A RANGE:20A	DAT.SAVE:PC CARD	NORMAL MEAS. :ON	INST. :ON	HARM. MEAS. :ON	AVE. :ON	E.ENERGY/DEM. :ON	MAX. :ON	WAVEFORM :ON	MIN. :ON	VOLT. QUALITY:OFF		START TIME:MANUAL		STOP TIME:MANUAL		SETUP																											
WIRING :3P3W2I	LOAD :LOAD1																																																
U RANGE:150V	INTER. :30min																																																
A RANGE:20A	DAT.SAVE:PC CARD																																																
NORMAL MEAS. :ON	INST. :ON																																																
HARM. MEAS. :ON	AVE. :ON																																																
E.ENERGY/DEM. :ON	MAX. :ON																																																
WAVEFORM :ON	MIN. :ON																																																
VOLT. QUALITY:OFF																																																	
START TIME:MANUAL																																																	
STOP TIME:MANUAL																																																	
SETUP																																																	

If a set value needs to be changed, press the F1 key (SETUP).


The Setup screen appears.


Change the set value. After the setup, press the ENTER key for returning to the Measure (Integrate) screen.

3 Wiring

After the above settings have been completed, carry out wiring, referring to Chapter 4 in this manual.


4 Integration Start

Check that the Integrate screen is displayed.	
	<p>Press START&STOP key. Integration starts according to the setting of the integration starting method.</p> <ul style="list-style-type: none">• STANDBY This appears until it becomes integration start time.• INTEG. This appears when it becomes integration start time, starting integration measurement.• END Integration stops according to the setting of the integration starting method.
	



<Forced end>

	Press START&STOP key displays the integration stop confirmation message.
	Press the ENTER key to forcibly stop integration. "END" appears on the screen.



NOTE



Even if you forcibly stop integration, data before forcible stop are stored into the PC card.

5.3 Measuring Harmonics

1 Settings

General 2/2

Setting Item	Description (setting value)
THP measure method	THD-F (fundamental wave)
Phase angle calculation method	Fundamental wave method
Harm. Graph Order	ALL ORD.

	<p>Displays SETUP.</p>  <p>The screen shows the following information: TOP MENU 2004-06/25 10:49:31 MEASURE (highlighted) SETUP (circled) FILE</p>
General 1/2 General 2/2	<p>Using right and left direction cursor key, display the General screen. Set up necessary items on the screen. For details, refer to Chapter 3 in this manual.</p>
Save 1/2 Save 2/2	<p>Using right and left direction cursor key, select Data Save screen. Set up necessary items on the screen.</p>

<General 2/2>

SETUP 2004/06/25
15:12:03
Page 2/2

GENERAL	SAVE	COMMUN		
▲ VAR METHOD : OFF SAMPLING METHOD : PLL 50Hz FREQUENCY SOURCE : U1 ZERO CROSS FILTER : OFF AVERAGE TIMES : 1 Wh DIG. DISPLAY : STANDARD INTERVAL Wh DIG. : STANDARD THD MEASURE METHOD : THD-F PA CALC. METHOD : FUNDAMENTAL WAVE ▼ HARM. GRAPH ORDER : ALL ORD.				
THD-F	THD-R			
F1	F2	F3	F4	F5

F1 : THD-F
F2 : THD-R

F1 : FUNDAME.WAVE
F2 : U1

F1 : ALL ORD.
F2 : ODD ORD.

< Save 2/2>

SETUP 2004/06/25
11:45:18
Page 2/2

GENERAL	SAVE	COMMUN	
E.ENERGY/DEM. : ON WAVEFORM DATA : ON NORMAL MEAS. : ON INST. : ON : ON AVE. : ON HARM. MEAS. : ON MAX. : ON : DETA. MIN. : ON			
▼ SAVE-TIME : 409DAYS 19:30:00			
ON	OFF		

F1 (Change)

HARMONIC OUTPUT ITEMS			
LOAD1	ON	I1 ON	I1 ON
LOAD2	OFF	I2 ON	CONTENT ON
LOAD3	OFF	I3 ON	PA ON
LOAD4	OFF	P ON	TOTAL ON
THD ON			
OUTPUT ORDER : SELECT			
* 01* 02* 03* 04* 05* 06* 07* 08* 09* 10 * 11* 12* 13* 14* 15* 16* 17* 18* 19* 20 * 21* 22* 23* 24* 25* 26* 27* 28* 29* 30 * 31* 32* 33* 34* 35* 36* 37* 38* 39* 40 * 41* 42* 43* 44* 45* 46* 47* 48* 49* 50			
ON	OFF		

<Exiting the Save 2/2 screen>

Press the ENTER key.

The screen returns to the Top Menu screen.

2

Wiring

After the above settings have been completed, carry out wiring, referring to Chapter 4 in this manual.

3 Measuring Harmonics

	<p>Display a Measure screen.</p> <p>TOP MENU 2004/06/25 10:49:25</p>																																																																		
	<p>Press the F1 (DISPLAY CHANGE) key to display the List screen.</p> <p>LIST LOAD1 INST. 2004/06/25 10:49:25</p> <table border="1"> <thead> <tr> <th></th> <th>I1</th> <th>I2</th> <th>I3</th> <th>Iave</th> <th>WIRING</th> </tr> </thead> <tbody> <tr> <td>LIST</td> <td>20.00</td> <td>20.10</td> <td>20.01</td> <td>20.04</td> <td>3P3W21</td> </tr> <tr> <td>POWER</td> <td></td> <td></td> <td></td> <td></td> <td>LOAD</td> </tr> <tr> <td>INTEGRATE</td> <td></td> <td></td> <td></td> <td></td> <td>1</td> </tr> <tr> <td>DEMAND</td> <td></td> <td></td> <td></td> <td></td> <td>U 150V</td> </tr> <tr> <td>ZOOM</td> <td></td> <td></td> <td></td> <td></td> <td>x 1.00</td> </tr> <tr> <td>HARMONIC</td> <td></td> <td></td> <td></td> <td></td> <td>A 20A</td> </tr> <tr> <td>WAVEFORM</td> <td></td> <td></td> <td></td> <td></td> <td>x 1.00</td> </tr> <tr> <td>VOLT.QUALITY</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>WIRING CHECK</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>WIRING DIAGRAM</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p>DISPLAY CHANGE ITEM CHANGE SETTING CHECK HOLD</p> <p>Using the cursor key, select HARMONIC (highlighted). Press the right direction cursor key to move to the Harmonic window. Select one of LIST, GRAPH and VECTOR using the up and down direction cursor key.</p>		I1	I2	I3	Iave	WIRING	LIST	20.00	20.10	20.01	20.04	3P3W21	POWER					LOAD	INTEGRATE					1	DEMAND					U 150V	ZOOM					x 1.00	HARMONIC					A 20A	WAVEFORM					x 1.00	VOLT.QUALITY						WIRING CHECK						WIRING DIAGRAM					
	I1	I2	I3	Iave	WIRING																																																														
LIST	20.00	20.10	20.01	20.04	3P3W21																																																														
POWER					LOAD																																																														
INTEGRATE					1																																																														
DEMAND					U 150V																																																														
ZOOM					x 1.00																																																														
HARMONIC					A 20A																																																														
WAVEFORM					x 1.00																																																														
VOLT.QUALITY																																																																			
WIRING CHECK																																																																			
WIRING DIAGRAM																																																																			
	<p>Press the ENTER key to display the Harmonic window.</p> <p>LIST 2004/06/25 10:49:25</p> <table border="1"> <thead> <tr> <th></th> <th>[A]</th> <th>[%]</th> <th>[deg]</th> <th>WIRING</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3.54</td> <td>100.0</td> <td>0.0</td> <td>3P3W21</td> </tr> <tr> <td>2</td> <td>0.00</td> <td>---</td> <td>---</td> <td>LOAD</td> </tr> <tr> <td>3</td> <td>3.01</td> <td>85.3</td> <td>172.0</td> <td>1</td> </tr> <tr> <td>4</td> <td>0.00</td> <td>---</td> <td>---</td> <td>U 150V</td> </tr> <tr> <td>5</td> <td>2.56</td> <td>60.9</td> <td>-12.1</td> <td>x 1.00</td> </tr> <tr> <td>6</td> <td>0.00</td> <td>---</td> <td>---</td> <td>A 20A</td> </tr> <tr> <td>7</td> <td>1.20</td> <td>34.0</td> <td>168.9</td> <td>x 1.00</td> </tr> <tr> <td>8</td> <td>0.00</td> <td>---</td> <td>---</td> <td></td> </tr> <tr> <td>9</td> <td>0.47</td> <td>13.3</td> <td>15.9</td> <td></td> </tr> <tr> <td>10</td> <td>0.00</td> <td>---</td> <td>---</td> <td></td> </tr> </tbody> </table> <p>TOTAL: 5.36 A f: 50.02Hz</p> <p>DISPLAY CHANGE ORDER CHANGE HOLD</p> <p>(The List screen is used as an example.)</p>		[A]	[%]	[deg]	WIRING	1	3.54	100.0	0.0	3P3W21	2	0.00	---	---	LOAD	3	3.01	85.3	172.0	1	4	0.00	---	---	U 150V	5	2.56	60.9	-12.1	x 1.00	6	0.00	---	---	A 20A	7	1.20	34.0	168.9	x 1.00	8	0.00	---	---		9	0.47	13.3	15.9		10	0.00	---	---												
	[A]	[%]	[deg]	WIRING																																																															
1	3.54	100.0	0.0	3P3W21																																																															
2	0.00	---	---	LOAD																																																															
3	3.01	85.3	172.0	1																																																															
4	0.00	---	---	U 150V																																																															
5	2.56	60.9	-12.1	x 1.00																																																															
6	0.00	---	---	A 20A																																																															
7	1.20	34.0	168.9	x 1.00																																																															
8	0.00	---	---																																																																
9	0.47	13.3	15.9																																																																
10	0.00	---	---																																																																

► For more details, refer to the CW240 User's Manual ◀


Chapter 6, "Configuring Settings"

Section 6.5, "Save Data Settings 2/2"

Chapter 7, "Making Measurements"


Section 7.6, "Measuring Harmonics"

<List>




TOTAL: Total rms value*: Total rms values are displayed if the elements to be measured are voltage (U) and current (I); total power values are displayed if the element to be measured is power (P).

<Graph>



<Vector>




F2 LOAD CHANGE

The load changes the F2 key is pressed.
(For measurement of multiple loads)

5.4 Displaying Waveform

One of the following three screens can be displayed:



1 Making Settings

	Displays SETUP.
	Top Menu screen
General 1/2	<p>Using right and left direction cursor key, display the General 1/2 screen. Set up necessary items on the screen. For details, refer to Chapter 3 in this manual.</p>
General 2/2	<p>Next, using up and down direction cursor key, display the General 2/2 screen. Also set up necessary items on the screen. For details, refer to Chapter 3 in this manual.</p>
Save 1/2	Using right and left direction cursor key, select Save 1/2 screen.
Save 2/2	Next, using up and down direction cursor key, select Save 2/2 screen.
Volt. Quality	Using the cursor key, select VOLT. QUALITY.
	This completes the settings, and return to the Top Menu screen.

2 Wiring


After the above settings have been completed, carry out wiring, referring to Chapter 4 in this manual.

3 Displaying Waveforms

	<p>Displays the Measure screen.</p>
	<p>Press the F1 key (DISPLAY CHANGE) for window callup.</p> <p>Using the cursor key, select WAVEFORM (highlighted). Press the right direction cursor key to move to the Waveform window. Using up and down direction cursor key to select one of VOLT. & CURR., VOLTAGE and CURRENT .</p>
	<p>Press the ENTER key to display the Waveform window.</p> <p>The VOLT. & CURR. (U&I) screen is used as an example.</p>

► For more details, refer to the CW240 User's Manual ◀

- Chapter 6, "Configuring Settings"
- Subsection 6.5.4, "Waveform Data"
- Chapter 7, "Making Measurements"
- Section 7.7, "Displaying Waveform"




<Vertical axis>

- The display range of the vertical axis is determined on the basis of the measurement range set.
 - U ZOOM and I ZOOM allow you to change the magnification (scaling) of the vertical axis.
- 1 → 2 → 5 → 10 → 20 → 1/3 → 1/2

<To switch a waveform screen>

Using up and down direction cursor key, switch the waveform screen.



5.5 Measuring Voltage Quality (Voltage Fluctuation)

1 Settings

Example:


Standard voltage: 100 V; Voltage swell: 120%; Voltage dip: 90%; Interruption: 10%; Hysteresis: 1%

Save 1/2


Setting Item	Description (Setting value)
Measure Start	TIME 2004/07/01 07:00
Measure Stop	TIME 2004/07/03 07:00
Interval Time	5 min
Data Save	PC card

Volt. Quality


Setting Item	Description (Setting value)	
Volt. Quality measurement	ON (performs voltage quality measurement)	
Standard Voltage	100V	
Threshold Value	Voltage dip Voltage swell Instantaneous voltage interruption	110% 90% 10%
Hysteresis	1%	

  	<p>Displays the Measure screen.</p> <p>TOP MENU</p>  <p>2004/06/25 10:49:51</p> <p>Top Menu screen</p>
General 1/2	<p>Using right and left direction cursor key, display the General 1/2 screen.</p> <p>Set up necessary items on the screen.</p> <p>For details, refer to Chapter 3 in this manual.</p>
General 2/2	<p>Next, using up and down direction cursor key, display the General 2/2 screen.</p> <p>Also set up necessary items on the screen.</p> <p>For details, refer to Chapter 3 in this manual.</p>
Save 1/2	Using right and left direction cursor key, select Save 1/2 screen.
Save 2/2	Next, using up and down direction cursor key, select Save 2/2 screen.
Volt. Quality	Using the cursor key, select VOLT. QUALITY.
	This completes the settings, and return to the Top Menu screen.

<Save 1/2>



<Volt. Quality>



2 Wiring

After the above settings have been completed, carry out wiring, referring to Chapter 4 in this manual.

3 Voltage Quality Measurement

	<p>Press the F1 key (DISPLAY CHANGE) for window callup.</p> <table border="1"><caption>LIST</caption><thead><tr><th></th><th>LOAD1</th><th>INST.</th><th>2004-06-28</th></tr></thead><tbody><tr><td>LIST</td><td>I1</td><td>19.99</td><td>A</td></tr><tr><td>POWER</td><td>I2</td><td>20.08</td><td>A</td></tr><tr><td>INTEGRATE</td><td>I3</td><td>20.02</td><td>A</td></tr><tr><td>DEMAND</td><td>Iave</td><td>20.03</td><td>A</td></tr><tr><td>ZOOM</td><td></td><td></td><td>U 150V</td></tr><tr><td>HARMONIC</td><td>PA</td><td>0.0</td><td>%</td></tr><tr><td>WAVEFORM</td><td>F</td><td>59.99</td><td>Hz</td></tr><tr><td>VOLT. QUALITY</td><td>DC1</td><td>0.0</td><td>mV</td></tr><tr><td>WIRING CHECK</td><td>DC2</td><td>0.0</td><td>mV</td></tr><tr><td>WIRING DIAGRAM</td><td></td><td></td><td>PULL</td></tr><tr><td>DISPLAY</td><td>ITEM</td><td>CHANGE</td><td>SETTING</td></tr><tr><td>CHANGE</td><td>CHANGE</td><td>CHECK</td><td>HOLD</td></tr></tbody></table> <p>Using the cursor key, select VOLT. QUALITY (highlighted).</p>		LOAD1	INST.	2004-06-28	LIST	I1	19.99	A	POWER	I2	20.08	A	INTEGRATE	I3	20.02	A	DEMAND	Iave	20.03	A	ZOOM			U 150V	HARMONIC	PA	0.0	%	WAVEFORM	F	59.99	Hz	VOLT. QUALITY	DC1	0.0	mV	WIRING CHECK	DC2	0.0	mV	WIRING DIAGRAM			PULL	DISPLAY	ITEM	CHANGE	SETTING	CHANGE	CHANGE	CHECK	HOLD
	LOAD1	INST.	2004-06-28																																																		
LIST	I1	19.99	A																																																		
POWER	I2	20.08	A																																																		
INTEGRATE	I3	20.02	A																																																		
DEMAND	Iave	20.03	A																																																		
ZOOM			U 150V																																																		
HARMONIC	PA	0.0	%																																																		
WAVEFORM	F	59.99	Hz																																																		
VOLT. QUALITY	DC1	0.0	mV																																																		
WIRING CHECK	DC2	0.0	mV																																																		
WIRING DIAGRAM			PULL																																																		
DISPLAY	ITEM	CHANGE	SETTING																																																		
CHANGE	CHANGE	CHECK	HOLD																																																		
	<p>The Volt. Quality screen appears.</p> <table border="1"><caption>VOLT.QUALITY END</caption><thead><tr><th></th><th>ALL</th><th>2004-06-28</th></tr></thead><tbody><tr><td>06/29</td><td>13:48:46.098</td><td>Dip</td></tr><tr><td>06/29</td><td>13:48:46.098</td><td>Int</td></tr><tr><td>06/29</td><td>13:48:49.439</td><td>Swe</td></tr><tr><td>06/29</td><td>13:48:49.439</td><td>Swe</td></tr><tr><td>06/29</td><td>13:48:53.418</td><td>Dip</td></tr><tr><td>06/29</td><td>13:48:53.418</td><td>Swe</td></tr><tr><td>06/29</td><td>13:48:53.418</td><td>Dip</td></tr><tr><td>06/29</td><td>13:48:53.438</td><td>Int</td></tr><tr><td>06/29</td><td>13:48:53.438</td><td>Int</td></tr><tr><td>06/29</td><td>13:48:55.099</td><td>Int</td></tr><tr><td>06/29</td><td>13:48:55.099</td><td>Int</td></tr><tr><td>06/29</td><td>13:48:55.119</td><td>Dip</td></tr></tbody></table> <p>DISPLAY ITEM SAVE HOLD CHANGE CHANGE /CLEAR</p>		ALL	2004-06-28	06/29	13:48:46.098	Dip	06/29	13:48:46.098	Int	06/29	13:48:49.439	Swe	06/29	13:48:49.439	Swe	06/29	13:48:53.418	Dip	06/29	13:48:53.418	Swe	06/29	13:48:53.418	Dip	06/29	13:48:53.438	Int	06/29	13:48:53.438	Int	06/29	13:48:55.099	Int	06/29	13:48:55.099	Int	06/29	13:48:55.119	Dip													
	ALL	2004-06-28																																																			
06/29	13:48:46.098	Dip																																																			
06/29	13:48:46.098	Int																																																			
06/29	13:48:49.439	Swe																																																			
06/29	13:48:49.439	Swe																																																			
06/29	13:48:53.418	Dip																																																			
06/29	13:48:53.418	Swe																																																			
06/29	13:48:53.418	Dip																																																			
06/29	13:48:53.438	Int																																																			
06/29	13:48:53.438	Int																																																			
06/29	13:48:55.099	Int																																																			
06/29	13:48:55.099	Int																																																			
06/29	13:48:55.119	Dip																																																			
	<p>Press the START&STOP key. Start integration according to the setting of the integration starting method. "STANDBY" appears until it becomes integration start time.</p>																																																				

► For more details, refer to the CW240 User's Manual ◀

Chapter 6, "Configuring Settings"


Subsection 6.7, "Voltage Quality Settings"

Chapter 7, "Making Measurements"

Section 7.8, "Measuring Voltage Quality
(Voltage Dip, Voltage Swell, or Instantaneous Interruption)"

● Voltage Quality Measurement

In this section, voltage dip, voltage swell or instantaneous interruption are measured and displayed.



● Stopping Integration Measurement

Integration stops according to the setting of the integration starting method. ("END" appears when it becomes integration stop time.)
As soon as integration stops, voltage quality data is written to the PC card.

● Forcibly Stopping Integration Measurement

If you want to stop integration measurement before it becomes integration stop time thus set, press the START&STOP key while integration is in progress.

☒ NOTE

Even if you forcibly stop integration, data before forcible stop are stored into the PC card.

6. Troubleshooting

This chapter describes how to handle problems that may arise with the CW240. If an error message has been displayed on the display screen, refer to Section 16.2, "Error Message Content and Actions" of the CW240 User's Manual.

Symptom	Things to Check	Reference Section
1) Nothing is displayed when the power switch is turned ON.	When using AC power • Confirm that the power cord is connected to the outlet correctly.	3.2.1
	• Confirm that the power supply is within the allowable power supply voltage range.	3.2.1
	When using battery power • Confirm that the battery case is correctly installed.	3.2.2 3.2.3
	• If a NiMH battery pack is being used, confirm that the battery has been sufficiently charged.	3.2.3
	• If an alkaline dry cell is being used, confirm that the battery has not dissipated. (Confirm that the battery is installed with correct polarity.)	3.2.2
2) Setting data is initialized when power is turned OFF.	• If the opening messages "RTC Initialized" and "Settings Initialized" are displayed when power is turned ON, the backup battery has become dissipated. Backup batteries cannot be replaced by the customer. Contact a service representative. The lifetime of the backup battery is approximately 10 years.	3.6
3) The measurement display value is incorrect.	• Check for the possibility of noise on the input signal.	
	• Confirm that the measurement probe and clamp are connected correctly.	3.3 3.4
	• Confirm that the frequency measurement element has been set correctly.	6.3.2 6.3.3
	• Confirm that the ambient temperature/humidity are within the specification's allowable range.	4.2

► For more details, refer to the CW240 User's Manual ◀

Section 6.2, "General Settings 1/2"

Section 6.3, "General Settings 2/2"

Symptom	Things to Check	Reference Section
4) Key operation cannot be done.	<ul style="list-style-type: none"> Confirm that key lock is not displayed at the upper right of the display area. 	15.3
5) Saving and writing to internal memory cannot be done.	<ul style="list-style-type: none"> Turn the power OFF then ON again. The problem may be resolved in the opening self-test. 	3.6
	<ul style="list-style-type: none"> It is possible that a power supply error, etc., occurred while the internal memory was being accessed. Format the internal memory in the file processing mode. Data saved in the internal memory will be lost. 	9.4
6) Saving and writing to the PC card cannot be done.	<ul style="list-style-type: none"> Confirm that the PC card has been inserted correctly. 	11.2
	<ul style="list-style-type: none"> Confirm that the PC card has been formatted. 	9.4
	<ul style="list-style-type: none"> Confirm that the capacity of the PC card has not been exceeded. 	11
7) Communication cannot be done through the RS-232 interface.	<ul style="list-style-type: none"> Confirm that the communication parameters of the CW240 and the controller, etc., match. 	6.6
	<ul style="list-style-type: none"> Confirm that the specifications of the cables connecting the CW240 and the controller, etc., are suitable for the purpose. 	10.2
8)Printing cannot be done.	<ul style="list-style-type: none"> Confirm that printer power is ON. (Refer to the printer's instruction manual.) 	10.3
	<ul style="list-style-type: none"> Confirm that connection cable specifications match. 	10.3
	<ul style="list-style-type: none"> Confirm that connection cables are connected correctly. 	10.3
	<ul style="list-style-type: none"> Confirm that the communication parameters of this device and the printer match. 	10.3
	<ul style="list-style-type: none"> Confirm that the print media has been set correctly. 	—
9) An error occurs in the opening message.	<ul style="list-style-type: none"> This is a hardware error. Contact to your local service representative. 	3.6

7. Memory Capacity (for Reference)

For saving all items of normal measurement data, electric energy/demand measured data, all items of harmonic measured data, waveform data and voltage quality measured data

Wiring		1P2W 4 loads	1P3W 2 loads	1P3W3I	3P3W2I 2 loads	3P3W3I, 3P4W	3P4W4I	3P3W+ 1P3W
No. of Data Items		5624	5052	3758	6888	4390	5002	7504
PC card (64MB)	1min	17hours	19hours	26hours	14hours	22hours	19hours	13hours
	60min	44days	49days	65days	35ays	56days	49days	32days
Internal Memory	1min	12min	13min	19min	8min	16min	13min	7min
	60min	12hours	13hours	19hours	8hours	16hours	13hours	7hours

1min, 60min : Interval time

► For more details, refer to the CW240 User's Manual ◀

Section 8.3, "Memory (Reference)"

8. Check Sheets

How to use these check sheets

This Quick Setup Manual comes with check sheets so that you can accurately and effectively carry out on-site measurements and settings. Please make use of these sheets, describing necessary setting items in advance.

Description on check sheets

- Setting of the current range (A range) varies depending on the clamp-on current probe to be used.
- Voltage/current input indication varies depending on the setting of the wiring and load.
- The shaded mark such as 150V indicates the default setting value upon system reset or when shipped from the factory.

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 1: General 1/2

Item	User setting	CW240 setting								
Wiring		<p><1> Change If you would like to change wiring, select one of the following items:</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr><td>3P3W+1P3W</td><td>3P3W2I</td></tr> <tr><td>3P4W4I</td><td>1P3W3I</td></tr> <tr><td>3P4W</td><td>1P3W</td></tr> <tr><td>3P3W3I</td><td>1P2W</td></tr> </table>	3P3W+1P3W	3P3W2I	3P4W4I	1P3W3I	3P4W	1P3W	3P3W3I	1P2W
3P3W+1P3W	3P3W2I									
3P4W4I	1P3W3I									
3P4W	1P3W									
3P3W3I	1P2W									
Number of Load	Load	<p>For 1P3W or 3P3W2I: <1> Load 1 <2> Load 2</p> <hr/> <p>For 1P2W: <1> Load 1 <2> Load 2 <3> Load 3 <4> Load 4</p>								
Wiring: 3P3W + 1P3W Load at 1P3W		<p>For 3P3W + 1P3W: <1> R-S <2> S-T <3> T-R</p>								
U range (voltage range)		Voltage inputs (U1-U3) differ depending on the setting of the wiring and load.								
Example	U1 U2 U3	<1> 150V <2> 300V 4 <3> 600V <4> 1000V								
VT ratio		1.00 0.01 to 9999.99								

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 2: General 1/2

Item	User setting	CW240 setting										
A range (current range)	Current input channels (CH) differ depending on the setting of the wiring and load.											
Example	CH1 A CH2 A CH3 A CH4 A	Setting of the current range (A range) varies depending on the clamp-on current probe to be used. Refer to Table 3. *1										
Current	CH1											
A range	500A											
CT ratio	0001.00											
Clamp-on current probe	96032											
CT ratio		1.00 0.01 to 9999.99										
Clamp-on probe *1		<p><1> Change If you would like to change the probe, select one of the following probes:</p> <table border="1"> <tr> <td>96035-2 (300A)</td> <td>96032</td> </tr> <tr> <td>96035-1 (3000A)</td> <td>96031</td> </tr> <tr> <td>96034-3 (1000A)</td> <td>96030</td> </tr> <tr> <td>96034-2 (2000A)</td> <td>96033</td> </tr> <tr> <td>96034-1 (3000A)</td> <td>96036</td> </tr> </table>	96035-2 (300A)	96032	96035-1 (3000A)	96031	96034-3 (1000A)	96030	96034-2 (2000A)	96033	96034-1 (3000A)	96036
96035-2 (300A)	96032											
96035-1 (3000A)	96031											
96034-3 (1000A)	96030											
96034-2 (2000A)	96033											
96034-1 (3000A)	96036											

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 3: Types of Clamp-on Current Probes *1

Model	-	User setting	Current range (A range)	
96036(2 A)	-		<1> 200 mA <2> 500 mA <3> 1 A <4> 2 A	
96033(50 A)	-		<1> 5 A <2> 10 A <3> 20A <4> 50 A	
96030(200 A)	-		<1> 20 A <2> 50 A <3> 100 A <4> 200 A	
96031(500 A)	-		<1> 50 A <2> 100 A <3> 200 A <4> 500 A	
96032(1000 A)	-		<1> 200 A <2> 500 A <3> 1000 A	
96034(3000 A)	Using the switch on a clamp-on probe to select current range			
	96034_1 (3000A)		<1> 300 A <2> 750 A <3> 1500 A <4> 3000 A	
	96034_2 (2000A)		<1> 200 A <2> 500 A <3> 1000 A <4> 2000 A	
	96034_3 (1000A)		<1> 100 A <2> 200 A <3> 500 A <4> 1000 A	
96035(3000 A)	Using the switch on a clamp-on probe to select current range			
	96035_1 (3000A)		<1> 300 A <2> 750 A <3> 1500 A <4> 3000 A	
	96035_2 (300A)		<1> 30 A <2> 75 A <3> 150 A <4> 300 A	

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 4: General 2/2

Item	User setting	CW240 setting
VAR METHOD		<1> ON <2> OFF
SAMPLING METHOD		<1> PLL synchronization <2> Fixed clock For fixed clock: <1> 50 Hz <2> 60 Hz
FREQUENCY SOURCE		For 1P3W or 1P3W3I: <1> U1 <2> U2
		For 3P3W2I: <1> U1 <2> U3
		For 3P3W3I, 3P4W, 3P4W4I, or 3P3W + 1P3W: <1> U1 <2> U2 <3> U3
ZERO CROSS FILTER		<1> ON <2> OFF
AVERAGE TIMES		<1> 1 <2> 2 <3> 5 <4> 10 <5> 20
Wh DISPLAY/ INTEGRATE		<1> Change If selected: Decimal point position and unit can be changed.
(Decimal point position)		<1> AUTO <2> 000000 <3> 00000.0 <4> 0000.00 <5> 000.000 <6> STANDARD
(Unit)		<1> mWh <2> Wh <3> kWh <4> MWh <5> GWh
E.ENERGY/DEM. within Interval time		<1> Change If selected: Unit can be changed.
(Unit)		<1> mWh <2> Wh <3> kWh <4> MWh <5> GWh
THD MEASURE METHOD		<1> THD-F With reference to fundamental wave <2> THD-R With reference to all rms values
PA CALC. METHOD		<1> Fundamental wave <2> U1
HARM. GRAPH ORDER		<1> ALL ORD. (1st-50th) <2> ODD ORD.

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 5: Save 1/2

Item		User setting	CW240 setting																						
MEASURE	START		<1> MANUAL	<2> TIME	<3> JUST																				
	STOP		<1> MANUAL	<2> TIME	<3> TIMER																				
	TIME	Start date		Stop date																					
		Start time		Stop time																					
SAVE	TIMER	(hh:mm:ss) to (hh:mm:ss)																							
	INTERVAL	<p><1> Change If selected: Select one of the following items:</p> <table border="1"> <tr> <td>Min</td> <td>Sec</td> <td></td> </tr> <tr> <td>60 min</td> <td>30 sec</td> <td></td> </tr> <tr> <td>30 min</td> <td>15 sec</td> <td></td> </tr> <tr> <td>15 min</td> <td>10 sec</td> <td></td> </tr> <tr> <td>10 min</td> <td>5 sec</td> <td>500 msec</td> </tr> <tr> <td>5 min</td> <td>2 sec</td> <td>200 msec</td> </tr> <tr> <td>2 min</td> <td>1 sec</td> <td>100 msec</td> </tr> <tr> <td>1 min</td> <td></td> <td>1 wave</td> </tr> </table>	Min	Sec		60 min	30 sec		30 min	15 sec		15 min	10 sec		10 min	5 sec	500 msec	5 min	2 sec	200 msec	2 min	1 sec	100 msec	1 min	
Min	Sec																								
60 min	30 sec																								
30 min	15 sec																								
15 min	10 sec																								
10 min	5 sec	500 msec																							
5 min	2 sec	200 msec																							
2 min	1 sec	100 msec																							
1 min		1 wave																							
TIME	<1> PC card <2> Internal memory																								
DATA SAVE	<1> PC card <2> Internal memory																								
HARD COPY	<1> PC card <2> Internal memory <3> Printer																								
FILE NAME	<1> Change If selected: Enter a file name.																								

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 6: Save 2/2

Item	User setting	CW240 setting
Electric Energy data Demand data		<1> ON Saves data. <2> OFF Does not save data.
WAVEFORM data		<1> ON Saves data. <2> OFF Does not save data.
Normal measurement data		<1> ON Saves data. <2> OFF Does not save data.
Harmonic data MEAS.		<1> ON Saves data. <2> OFF Does not save data.
Detailed items of Harmonic data MEAS. DETA.		<1> Change If selected: The Detail screen appears. Refer to Table 7 for details.
Common to normal measurement and harmonic measurement	INST.	<1> ON <2> OFF
	AVE	<1> ON <2> OFF
	MAX.	<1> ON <2> OFF
	MIN.	<1> ON <2> OFF

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 7: Save 2/2

Item	User setting	CW240 setting
LOAD	Displays the number of loads.	
	LOAD 1	<1> ON <2> OFF
	LOAD 2	<1> ON <2> OFF
	LOAD 3	<1> ON <2> OFF
	LOAD 4	<1> ON <2> OFF
ELEMENT	Element display varies depending on the setting of the wiring.	
	U1	<1> ON <2> OFF
	U2	<1> ON <2> OFF
	U3	<1> ON <2> OFF
	P	<1> ON <2> OFF
	I1	<1> ON <2> OFF
	I2	<1> ON <2> OFF
	I3	<1> ON <2> OFF
	I4	<1> ON <2> OFF
LEVEL		<1> ON <2> OFF
CONTENT		<1> ON <2> OFF
HARM. PA		<1> ON <2> OFF
TOTAL VAL		<1> ON <2> OFF
THD		<1> ON <2> OFF

Check Sheet No.	
	File name:
	Site name:
	Prepared by:
	Date issued:

Table 8: Harmonic Output Order Setup

Item	User setting	CW240 setting																																																		
OUTPUT ORDER		<p><1> Saves ALL ORD. (1st to 50th) <2> Saves ODD ORD. <3> Saves EVEN ORD. <4> Allows you to select harmonic orders individually.</p>																																																		
<1> ON <2> OFF																																																				
An asterisk (*) is displayed for a selected order number.																																																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 12.5%;">01</td><td style="width: 12.5%;">02</td><td style="width: 12.5%;">03</td><td style="width: 12.5%;">04</td><td style="width: 12.5%;">05</td><td style="width: 12.5%;">06</td><td style="width: 12.5%;">07</td><td style="width: 12.5%;">08</td><td style="width: 12.5%;">09</td><td style="width: 12.5%;">10</td></tr> <tr> <td>11</td><td>12</td><td>13</td><td>14</td><td>15</td><td>16</td><td>17</td><td>18</td><td>19</td><td>20</td></tr> <tr> <td>21</td><td>22</td><td>23</td><td>24</td><td>25</td><td>26</td><td>27</td><td>28</td><td>29</td><td>30</td></tr> <tr> <td>31</td><td>32</td><td>33</td><td>34</td><td>35</td><td>36</td><td>37</td><td>38</td><td>39</td><td>40</td></tr> <tr> <td>41</td><td>42</td><td>43</td><td>44</td><td>45</td><td>46</td><td>47</td><td>48</td><td>49</td><td>50</td></tr> </table>			01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
01	02	03	04	05	06	07	08	09	10																																											
11	12	13	14	15	16	17	18	19	20																																											
21	22	23	24	25	26	27	28	29	30																																											
31	32	33	34	35	36	37	38	39	40																																											
41	42	43	44	45	46	47	48	49	50																																											

Table 9: Communication

Item	User setting	CW240 setting						
RS-232 CONNECT		<1> Printer <2> PC						
BAUD RATE		<p><1> Change If selected: Select one of the following items:</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <tr> <td style="width: 50%;">38400 bps</td><td style="width: 50%;">4800 bps</td></tr> <tr> <td>19200 bps</td><td>2400 bps</td></tr> <tr> <td>9600 bps</td><td>1200 bps</td></tr> </table>	38400 bps	4800 bps	19200 bps	2400 bps	9600 bps	1200 bps
38400 bps	4800 bps							
19200 bps	2400 bps							
9600 bps	1200 bps							
DATA LENGTH		<1> 7 <2> 8						
PARITY		<1> EVEN <2> ODD <3> NONE						
STOP BIT		<1> 1 <2> 2						
FLOW CONTROL		<p><1> OFF/OFF <2> XON/XON <1> XON/RS <2> CS/RS</p>						

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 10: Voltage Quality

Item		User setting	CW240 setting		
VOLT. QUALITY MEAS.			<1> ON Measures voltage quality. <2> OFF Does not measure voltage quality.		
STANDARD VOLTAGE			<1> Change If selected: Select one of the following items:		
THRESHOLD VALUE	SWELL		1000 V	277 V	120 V
	DIP		600 V	240 V	110 V
	INTERRUPTION		480 V	230 V	101 V
HYSTERESIS			380 V	220 V	100 V
			346 V	208 V	
			202 V		
			200 V		
			110%	0 to 200%	
			90%	0 to 100%	
			10%	0 to 100%	
			Percent indication with respect to standard voltage (common to voltage swell, voltage dip, voltage interruption)		
			1%	0 to 10%	

Check Sheet No. _____

File name:	
Site name:	
Prepared by:	
Date issued:	

Table 11: Hardware

Item	User setting	CW240 setting
LANGUAGE		<1> Change If selected: ENGLISH
BEEP		<1> ON Generates a beep each time an operation key is pressed. <2> OFF Turns off the beep.
BACKLIGHT AUTO OFF		<1> ON Automatically turns off backlight. <2> OFF Does not automatically turn off backlight.
LCD CONTRAST		Sets LCD contrast (1 to 8).
ID NUMBER		001 001 — 999
DATE AND TIME	Year/Month/ Hour/Min/Sec	Sets date and time (accurate time entry).

YOKOGAWA ♦

Yokogawa M&C Corporation

YOKOGAWA M&C CORPORATION

International Sales Dept.

2-9-32 Nakacho, Musashino-shi, Tokyo, 180-8750 Japan
Phone: 81-422-52-5716 Facsimile: 81-422-55-8954

YOKOGAWA CORPORATION OF AMERICA (U.S.A.)

Phone: 1-770-253-7000 Facsimile: 1-770-251-2088

YOKOGAWA EUROPE B. V. (THE NETHERLANDS)

Phone: 31-334-64-1611 Facsimile: 31-334-64-1610

YOKOGAWA ENGINEERING ASIA PTE. LTD. (SINGAPORE)

Phone: 65-6241-9933 Facsimile: 65-6241-2606

YOKOGAWA AMERICA DO SUI S. A. (BRAZIL)

Phone: 55-11-5681-2400 Facsimile: 55-11-5681-1274

YOKOGAWA MEASURING INSTRUMENTS KOREA CORPORATION (KOREA)

Phone: 82-2-551-0660 to -0664 Facsimile: 82-2-551-0665

YOKOGAWA AUSTRALIA PTY. LTD. (AUSTRALIA)

Phone: 61-2-9805-0699 Facsimile: 61-2-9888-1844

YOKOGAWA INDIA LTD. (INDIA)

Phone: 91-80-2227-1513 Facsimile: 91-80-2227-4270

YOKOGAWA SHANGHAI TRADING CO., LTD. (CHINA)

Phone: 86-21-6880-8107 Facsimile: 86-21-6880-4987

YOKOGAWA MIDDLE EAST E. C. (BAHRAIN)

Phone: 973-358100 Facsimile: 973-336100

LTD. YOKOGAWA ELECTRIC (RUSSIAN FEDERATION)

Phone: 7-095-737-7868 Facsimile: 7-095-737-7869

KIM3E-2004.7